

PT

004887-004892-0209

Ship's name

"STIRLINGSHIRE"

Port

HUL

No. 70155

Class is subject to

Last survey date 26.11.64

For conditions of class - See previous endorsement.

S.R.L. Appendix (as before ~~XXXXXXX~~)

Nature of present survey (afloat and in drydock)

Docking. Repairs to damage (H.W.) and
to part of deferred items as above.

Recommendation

SUBMITTED record of DS 11.64 be assigned,
subject to local corrosion on sternframe (s.s)
and indented shell plate No.10 in 4th below
sheer (p.s), indented shell plate etc. No.7
from aft 3rd below sheer (s.s) and set in shell
plates G.8 and H.7 (s.s. from aft) being specially
examined and dealt with as necessary next dry-
docking also to 15 fathoms of chain cable being
supplied at the earliest opportunity, without
other conditions.

DS 11.64 Subject.without.

IN S.R.L. APPENDIX

Sheerstrake plating abreast fore and main masts (p.s) set in.
Shell plating (p & s) indented.
(External cathodic protection fitted 2.64)

ENGINEERS TO NOTE

DL 23/12/64