

JE

LLOYD'S REGISTER OF SHIPPING



P. O. Box. No. 4922
Cablegrams: "Lloydreg", Karachi

RECEIVED
10 JAN 1966
SAFE DEPOSIT CHAMBERS
McLEOD ROAD
KARACHI
Ans. XSEI

Telephone: 30429

5th January, 1966

Dear Sir,

s.s. "MANSOOR"

The subject vessel is at present under survey at this port. Although the Owners first intention was to carry out the Special Survey they now request for postponement until January, 1967 in view of that the ship will most probably be scrapped by that time.

It is further requested that renewal of the set up keel plates Nos.1 and 2 may be further deferred if on examination in drydock the plates and its temporary repairs would be found to continue efficient.

The General Service Pump Sea Suction Valve Chest will be renewed this time.

I am, Dear Sir,
Yours faithfully,

(J. van Son)
For The Surveyors.

The Secretary,
LONDON.



© 2020

Lloyd's Register
Foundation

004887-004892-0245

REPORT

CRH
5/5 KRH 7/12 GESS

(NON PAV. 1)
101 THE UNIVERSITY

112 1890
101 THE UNIVERSITY

The General Services Administration
will be pleased to provide you with a copy of the report.

To determine the extent of the problem and to identify the causes of the problem, the following information is being requested:

1. A list of all the units in the system which are affected by the problem.
2. A description of the problem as it exists in each of the units listed in (1).
3. A description of the steps which have been taken to date to correct the problem.

"FOODS" . . . 2

112 1890

101 THE UNIVERSITY

101 THE UNIVERSITY

KYIVACI

101 THE UNIVERSITY

101 THE UNIVERSITY

AUDIO BOND

MADE IN AUSTRALIA



© 2020
Lloyd's Register
Foundation