

10 DEC 1965

SHIP'S NAME "MANSOOR"

PORT CHG

No. 815

LAST SURVEY DATE 8.11.65.

CLASS IS SUBJECT TO General service pump sea suction valve chest being renewed by 8.65.

The Surveyor reports damage to the four propeller blade tips by contact with a portoon mooring chain at Chittagong on 23.10.65 and defers repairs until dry docking. He recommends the propeller be examined & dealt with as found necessary on arrival at Karachi.

He also reports local corrosion of a boiler tube plate, wrapper plate & rivet head, made efficient. He defers repairs of a permanent nature & recommends the starboard boiler centre furnace back tube plate & wrapper plate be examined & dealt with as found necessary on arrival at Karachi, its boiler pressure not to exceed 150 P.S.I. meantime.

It is submitted that this vessel is eligible to remain as CLASSED. subject as above and as now recommended.

[Signature]
9.12.65.

Subject Item:- Valve chest will be dealt with at Karachi.



© 2020

Lloyd's Register
Foundation

004887-004892-0248