

Ship's name **MANSOOR.**

Port **COLOMBO
KARACHI**

27 MAR 1963
S358
No. **KRH/74**

Class is subject to **NIL**

Last survey date **7-3-63
25-2-63**

M.B.S. DUE 12-62 NOW ~~PARTLY~~ HELD 2-63
S.P.S. DUE 12 62 NOW PARTLY HELD 2-63

REPAIRS:- SURVEYOR REPORTS MAIN CIRC. PP. IMPELLER SHAFT FRACTURED
NOW REPAIRED.
SURVEYOR RECOMMENDS THAT THIS SHAFT BE SPECIALLY
EXAMINED & DEALT WITH AS FOUND NECESSARY BEFORE THE
END OF MAY 1963.

It is submitted that
this vessel is eligible to
remain as **CLASSED** WITH FRESH RECORD OF
M.B.S. 2-63 NOW. & S.P.S. 2-63 WHEN THE SURVEY HAS
BEEN COMPLETED. SUBJECT AS RECOMMENDED.

23-3-63
TO COMPLETE S.P.S.:- ONE LENGTH SMOKEBOX SATURATED STEAM PIPE.
TO BE RENEWED.