

30 JAN 1963

Ship's name

"WAPPU"

Port

HFS

No. 494

Last survey date 12.1.63.

Class is subject to

Metallock repairs to Main engine LP cast iron column under pump lever bracket being examined and dealt with as necessary before the end of January 1963 (18 months limit).

SRL item

Now examined and found efficient for the meantime but the surveyor recommends the Metallock repairs to Main engine LP cast iron column under pump lever bracket being specially examined before the end of January 1964 (12 months limit).

IT IS SUBMITTED that this vessel is eligible to remain as classed subject as now recommended.



© 2021

Lloyd's Register
Foundation

28.1.63.