

Ship's name "BOUNDARY"

Port

Drb.

No.

9976

Ship is subject to

NONE.

Last survey date

22.9.62

35 OCT 1962

S.L. Appendix (as before ~~XXXXXXXX~~)

Area of present survey (afloat ~~XXXXXXXXXXXXXXXX~~)

Examination of temporary repairs to corroded shell plate.

Recommendation

SUBJECT to corroded shell plate at after end of
after cargo hold (s.s.) being examined and dealt
with as necessary before loading another cargo.

Now. Subject

S.R.L. APPENDIX.

adder stock twisted 20°)



© 2020

Lloyd's Register
Foundation

004900-004905-0155