



# LLOYD'S REGISTER OF SHIPPING

Cato House, 340, Smith Street, Durban

Telegrams: Lloydsreg

P.O. Box 170

Telephone: 2-4092

A I R M A I L

RECEIVED

22nd September, 1962.

27 SEP 1962

Dear Sir,

s.s. "BOUNDARY"

We would refer to our Rtn. 3, dated 24th August, 1962, when we entered the above named ship as being under survey for hull repairs.

We now have to advise you that we attend the ship on account of reported leakage and found that temporary repairs had been effected by the ship's staff.

We however were not satisfied and recommended further repairs before loading another cargo. The Owners agreed to our recommendations and stated they would advise us when work was commenced.

As we heard nothing further from the Owners we made enquiries and the Owners stated that the ship is laid up pending a decision by the Board of Directors as to whether this ship should be sold as scrap or continue to trade until the expiry date of her certificates.

The Owners stated further that as soon as a decision has been reached they will notify us.

If the ship continues to trade she will be submitted for further survey and repairs. The Main Boiler Survey, which is overdue will also be carried out before sailing.

In the meantime we have issued an Interim Certificate, subject to further repairs in way of after hold, starboard side, before loading another cargo.

Yours faithfully,

T. H. NOEL.

The Secretary,  
LONDON.



Lloyd's Register  
Foundation

004900-004905-0156

