

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C. 3.

18th September, 1937.

Dear Sir,

S.

With reference to Glasgow First Entry Report No. 58845 on the steamer "DONAGHADEE" it is concluded that the after end of the screwshaft liner is made water tight in the propeller boss. I shall be glad however if you will be good enough to enquire of the Surveyor and let me know whether this is so.

I am, Dear Sir,

Yours faithfully,

Clerk to the  
Classification Committee.

The Secretary,

GLASGOW.



© 2020

Lloyd's Register  
Foundation

004906-004917-0062