

"DJATINEGARA"

The question of Re-classification was raised in March, 1952, and the Owners were informed that a General Examination of the machinery should be carried out, a complete Boiler Survey held and both screwshafts examined. A survey was in due course held but re-instatement of class was withheld on account of the centre boiler requiring extensive repairs and both screwshafts requiring examination. The screwshafts ~~was~~ subsequently drawn and examined but the centre boiler was not repaired.

The question of Re-classification has again been raised in the attached cable from the Kobe Surveyors.

On account of the length of time that has now elapsed since the last Machinery Survey was held it will now be ~~en~~ necessary for a complete examination of the machinery to be held, a complete Boiler Survey and a Steam Pipe Survey to be held, & extensive repairs are necessary for the centre boiler.

IT IS SUBMITTED the Kobe Surveyors to be advised accordingly.

4
Note Ksb (H)
RE



© 2020
3.9.54.

Lloyd's Register
Foundation

004937-004945-0141