



Lloyd's Register of Shipping,

Lloyd's Bank Chambers,

Middlesbrough, 20th October 1940.

Reference

Dear Sir,

s.s. "STUART PRINCE"

With reference to our First Entry Report No.16917 on the above vessel, we beg to inform you that several blow holes were found near the bottom end of the low pressure cylinder. In agreement with the Superintendent Engineer a screwed plug was fitted in the largest hole, the metal in way being found sound.

The Superintendent Engineer stated that owing to war conditions, it had not been advisable to renew this cylinder and in our opinion this cylinder is in a safe working condition.

We are, Dear Sir,

Yours faithfully,

The Surveyors,

Per:- *R. J. Easthope*

The Secretary,
LONDON.



© 2020

Lloyd's Register
Foundation

004946-004953-0224

W. H. L. 4/11/60

Do
Rg



© 2020

Lloyd's Register
Foundation