

Lloyd's Register of Shipping.

Ship's Name S.S. "FORT HAMILTON"

Official No. 10300

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines
in

New York

January 9, 1956

A 2" diameter gun-metal non-return flap valve fitted to port side shell
plating above the freeboard deck on the after crews accommodation space.

The valve was fitted with through studs to a suitable circular doubling
plate, 10" diameter welded to the ship side on both sides.

Size of opening 2" diameter.

J. J. Hendley
SURVEYOR TO LLOYD'S REGISTER

OF SHIPPING

Notes *1002* = 9 FEB 1956

