

17 FEB 1960

SHIP'S NAME "HAAKON HAUAN" REPORT Osl. No. 8911

VC

Outstanding Conditions of Class: SUBJECT to temporary repairs to
 A. 7 & 9 (p.s) and D.13 in way of bilge keel (p.s) also
 obttom riveting in way of No.6 (s.s.) and No.3 (p.s)
 cargo tanks being examined and dealt with as necessary
 before end of July, 1960.

S.R.L. Appendix. (As before ~~or None~~)

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Temporary repairs on account of heavy weather damage.

Recommendation:

SUBJECT as above, and to shell plating in 'F' strake
 (s.s.f) (fractured) in way of deep tank being examined
 and dealt with as found necessary by the next drydocking.

As now. SUBJECT.

IN S.R.L. APPENDIX.
 (Vessel is hogged 8")



© 2020

 Lloyd's Register
 Foundation

John
 18/2/60