

Chief Surveyors.....

Received from Chief Surveyors.....

S NAME "ULMARRA" REPORT No.

For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/02.)

of Survey..... ~~XXXXXX~~

This ship (32 years old) is classed BS\* and the last record of drydocking is 1,54.


A SPECIAL SURVEY (D) becomes due 3,58.

In a letter dated 7.10.55 the Sydney Surveyors advise Owners' request for the class of this ship to be withdrawn.

IT IS ACCORDINGLY SUBMITTED the class of this ship be withdrawn at Owners' request.

WITHDRAW CLASS and  
INSERT IN R.B.

Class withdrawn at Owners' request 10,55.



13.10.55.



© 2020

Lloyd's Register  
Foundation

CLASSIFIED

(3)

54  
...ers are  
Co