

WRECK  
SECTION  
No 830 c


OK  
Growth  
1/5/61


MOUNT OLYMPUS

LOAN WALL 1607

Mr. Sharpe of Clyde & Co (Solicitors) phoned stating  
at Rugby in 1958  
that it is alleged the repairs to the HP IP & LP bottom  
ends, 6 essential straps upper valves & 6 main bearing  
~~lower~~ lower valves (remetalising) were faulty.

He desires to be informed whether, prior to 1958,  
there were other repairs of a similar nature.

  
18/1/61

Shm documents <sup>only</sup> on production of  
Authorisation Lr. from Owners  
- per RRC 18/1/61 

WRECK  
SECTION  
No 830 c



© 2021

Lloyd's Register  
Foundation

005013-005019-0164