

29 SEP 1959

4E

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

NAME..... MOUNT OLYMPUS

REPORT

P.E1

No. 996

MBS due 7.59, partly held now.

The Surveyor reports some temporary repairs effected to the combustion chamber back plate stays in the port and starboard main boilers and recommends that the class now be made subject to temporarily repaired combustion chamber back plate stays being permanently repaired before the end of December, 1959.

IT IS SUBMITTED this vessel is eligible to remain as classed with fresh record of MBS 7.59 when the survey has been completed as per this report, subject as recommended.

[Handwritten Signature]

28.9.59



© 2021

Lloyd's Register Foundation

005013-005019-0179

and noted
ce 24/8/59