



Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME *Clausina*

Rpt. *Ret.* No. *27514*
Rpt. *Ans.* No. *15-403*
" " *15-15-7*

Notes of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.

of Engine

Pil Engine 4 S.C.S.A.
8 Cy. 25-9/16" - 55 1/8"



~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of approved type

Yes
No

This vessel's machinery appears to have been built in accordance the Rules and the approved plans, and it is submitted she is able to be classed *+LMC 10.38.*

DB 180 lb.

L.Y.
15/11/38.

Request Rpt. to return on Auxiliary Engine



© 2021

Lloyd's Register Foundation

Mr Stephenson



© 2021
Lloyd's Register
Foundation

IE