

COPY

# LLOYD'S REGISTER OF SHIPPING



Port MANCHESTER

3rd February, 1961.

This is to Certify that I have  
 Surveyed the Machinery of <sup>S.H.</sup> the "MANCHESTER PROGRESS" 7346 gross tons of  
 Manchester while the vessel lay in drydock and afloat at this port on the  
 2nd November, 1960 for Docking Completion of H.S., Commencement of M.B.S and SPS,  
 and that I will transmit to the Committee of Lloyd's Register of  
 Shipping, London, a Report stating that all recommendations made by  
 me in connection therewith have been carried out to my satisfaction; also  
 that I will Recommend that in the case of this Vessel the following  
 Survey Records be made in the Supplement to the Register Book  
 E.S. 1-61, SPS 1-61, MBS 1-61 when the survey has been completed,  
 and that her Machinery Classification Record be continued in the Book.  
 subject to the main condenser starboard water box door being renewed  
 by 1/62 (12 months limit).

Parts now examined:  
 (C.S. Items only)

*P.K. Coles*

Engineer Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

(P.K. COLES),

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

