

ARCOs.

F.E.

Received by Chief Ship Surveyor 26.9.18

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Steel S.S. War Javelin Rpt. live No. 71285

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 62-95 Depth "d" 22.19Framing: Table No. 3 page 11 Description Bulb angle as approvedLongitudinal No. 17915Proportions  $\frac{\text{Length}}{\text{Depth}} =$ Upper Deck Sheerstrake as approved

The downton pump has not been fitted as approved in  
Standard Vessels.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\nabla$  100 A-1 (Steel) as recommended.

1.5% (Steel) Well Dr

Cell 5.13 228' 568L. F.P.T. 122G. A.P.T. 234L

F.K. 713H. pl. cm - Lloyd's Reg. P28 Q77 B56 F28

The Certificate of Classification, to be endorsed  
 "Cargo battens not fitted," and the same  
 notation to be printed in the Register Book.

M  
27.9.18



© 2019

Lloyd's Register  
Foundation

005047-005055-0068