

21 FEB 1964

Ship's name "ATHELSULTAN" Port DRB No. 10660
Last survey date 25.1.64.

Class is subject to

indented shell plates G.8 and H.7 (s.s.a), No.3 in 1st below
 and Nos.3 & 4 in 2nd below sheer (s.s.f) being specially
 examined and dealt with as necessary next drydocking, and to
 indented shell plates G.15 & 16, H.17 (s.s.from aft) being
 specially examined and dealt with as necessary by the S.S.

S.R.L. Appendix (as before ~~XXXXXXXXXX~~)

Surveys due SPECIAL SURVEY (D) due 3,64. Postponement until 9,64
 approved 13.1.64. G.E. Held Cff.11,63. S.S. commenced
 Cff.11,63.

Nature of present survey (afloat ~~as per XXXXXXXXXXXXX~~)

Damage - contact, involving shell plates G.15 & 16 and adjacent
 'H' strake plate in way of No.3 cargo tank. It should be
 noted that this plating is already against the class of
 this ship.

Is interim certificate in order

Yes/No/None

Items outstanding ~~XXXXXXXXXXXXXXXXXXXX~~

PORTION OF SURVEY HELD:-

Examined Internally: F.P. tank,
 Examined Internally & Tested: Fwd. deep tank (p.s),
 Examined and tested: After pump room.
 Examined: Upper deck plating in way of galley.

SS proposed to be completed by

Recommendation SUBJECT as above.

As Now Subject.

IN S.R.L. APPENDIX

Side shell plating (p & s) slightly indented.

S.S. PART HELD.



© 2020 ^{S.P.R.} 21/2/64

Lloyd's Register
 Foundation