

No. I/975.

DUPLICATE


THE BRITISH CORPORATION REGISTER OF SHIPPING AND AIRCRAFT

ANNUAL SURVEY

No. in Reg. Book Official No. 181799. Gross Tons 10712.
 Name "GLADYS MOLLER".
 Owners Mollers Hongkong Ltd. Port of Registry London.
 Built by Sun Shipbuilding & Dry Docking Co. Chester When 8-1945.
 (No. 2894) Pa.,
 Date last Survey Decr. 1947. Expiry date of Load Line Certificate 28th July, 1950.
 Last Visit 8-2-1949. Last Visit 24-2-49. Number of Visits 6.

TO THE REGISTER AIRCRAFT

ITEM EXAMINED	CONDITION FOUND	RECOMMENDATIONS	DATE EFFECTED
WAYS (including small ways) on freeboard deck, girders, stays and stiffeners	Good.		
Deck girders	-		
Hinged steel covers,	Good.	Coamings & Covers scaled to bare metal and coated, & hinges & worm screws overhauled.	10-2-49.
Plating (state number per section)	-		
Deck battens	-		
Stays and fittings	-		
Is supply including reserves adequate?	-		
Structure on superstructure including R Q D, stays and stiffeners	Good.		
Deck girders	-		
Hinged steel cover,	Good.		
Plating (state number per section)	-		
Deck battens	-		
Stays and fittings	-		
Is supply including reserves adequate?	-		



Rs. _____ Advised _____
 _____ Paid _____
 Rs. _____

Chief Surveyor.



© 2020

See Dry docking Report
 No. I/976 dated 26-2-49.

Lloyd's Register
 Foundation


005069-005074-0180

ITEM EXAMINED	CONDITION FOUND	RECOMMENDATIONS
3. Within superstructures not intact or not protected by Class I closing appliances	-	
Coamings	-	
Beams	-	
Fore and afters	-	
Covers	-	
Tarpaulins (state number per hatchway)	-	
Cleats and battens	-	
Wedges (Is supply including spares adequate?)	-	
Tarpaulins, battens, covers, &c., to be examined in place as well as separately.		
VENTILATORS IN EXPOSED POSITIONS		
4. To Spaces below freeboard deck	Good.	
Coamings, supports and deck connections	Good.	
Closing arrangements	Good.	
5. To spaces below decks of superstructures which are intact or have Class I closing appliances	Good.	
Coamings, their supports and deck connections	Good.	
Closing arrangements	Good.	
AIR PIPES		
6. Exposed on freeboard and superstructure decks	Good.	
Closing arrangements	Good.	
7. Within partially enclosed superstructures	Good.	
Closing arrangements	Good.	
MACHINERY CASINGS		
8. Casing Top	Good.	
Fiddley openings, covers and fastenings	Good.	
Skylight, fastenings, covers and lashings	Good.	
9. Exposed on freeboard and R Q D	Good.	
Doors and fastenings	Good.	
10. Exposed on superstructure decks except R Q D	Good.	
Doors and fastenings	Good.	
11. Within partially enclosed superstructures	Good.	
Doors and fastenings	Good.	

EXAMINED	CONDITION FOUND	RECOMMENDATIONS	DATE EFFECTED
Anchor scuttles	-		
Passages, including lockhouses enclosing openings, fastenings, covers	Good.	Dogs overhauled.	14-2-49.
Appliances for opening in superstructure	Hinged steel watertight door and portable steel plate secured by hook bolts.	All dogs overhauled.	14-2-49.
Fore end	Hinged steel watertight doors.	" " "	14-2-49.
Aft end	Hinged steel watertight doors & portable steel plate secured by hook bolts.	" " "	14-2-49.
Cargo and coaling	-		
Deck and superstructure	-		
Other requirements of Annual Survey	Good.	All overhauled.	20-2-49.
Large pipes	Good.		
Sanitary	Good.		
Dead	Good.		
Access to quarters	Good.		
Fittings and material	Good.		
Ports	Nil.		
Bars	-		
Anchor or special appliances	Good.		
Included in fore-	-		
	Checked and repainted.		

Particulars of any change from the Conditions given on the Load Line Certificate of L. L. 4 D Form.

New Engine Room Skylight with hinged steel covers and Galley Skylight and ventilators fitted. See attached plans.



Lloyd's Register Foundation

Do. of 8

Certificate A.—To be signed by each surveyor in respect of a partial or complete survey of preceding items on a British ship.

The undersigned surveyed the following items in the foregoing report:—

INDEX NOS. OF ITEMS EXAMINED Insert "all" if complete survey carried out	SIGNATURE OF SURVEYOR	PLACE State name of dry dock or where if afloat
All	<i>J. J. Walmsley</i>	Bombay

Certificate B.—To be signed by the surveyor completing the survey on a British ship

I am satisfied—

- (i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports, and the means of access to the crew's quarters have been maintained in the ship in as effective a condition as they were in when the Certificate was issued; and
- (ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

No. 2894. I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor... *J. J. Walmsley* ... Place... **Bombay, India.** ... Date... **24th**

OTHER REQUIREMENTS OF ANNUAL SURVEY.

ITEM EXAMINED	CONDITION FOUND	RECOMMENDATIONS
25. Watertight bulkheads doors	Good.	
26. Sluice valves	Good.	
STEERING ARRANGEMENTS 27. Steering gear.	Good.	Surveyed by Engineer and Surveyor.
28. Control rods, telemotor system, &c.	Telemotor Good.	-do-
29. Chain rod and connections	-	
30. Spring buffers	-	
31. Fairleads	-	
32. Brake	-	
33. Auxiliary steering gear (state date of trial)	Good.	Surveyed by Engineer Surveyor.
34. Spare gear (state particulars)	-	
35. Ship's record examined (state date when claims last annealed)	Not produced.	



© 2020

J. J. Walmsley
Surveyor to the British Corporation
Lloyd's Register
Foundation