

26th October, 1953.

Dear Mr. Willis,

The Engineer Reports Department in checking the reports of the "EDDYCREEK" have drawn attention to the fact that Glasgow Report 5a No.79847 does not contain all the relevant details required (size of safety valves fitted etc.).

I am therefore enclosing this report and perhaps you would be so good as to have the necessary details inserted, or a supplementary report provided if you consider this the best course.

With kindest regards,
Yours sincerely,

C. R. Willis, Esq.,
GLASGOW.



© 2020

Lloyd's Register
Foundation

005082-005088-0130