

"EDDYCREEK"

Gls.80907

Gls.79847

Before this case receives the consideration of the Committee the Glasgow Surveyors should be requested to forward a boiler report with all relevant details (size of safety valves fitted etc.) which were not supplied in Glasgow Report 79847.

gs.

20.10.53.



© 2020

Lloyd's Register
Foundation

005082-005088-0138