

"NOORDAM"

RMC Rot. 38815

An additional cargo refrigerating installation has been fitted on board under survey in accordance with the approved plans and Secretary's letter\$.

All necessary tests have been satisfactorily carried out.

IT IS SUBMITTED this additional installation merits approval with record of ~~2-5~~ (No. 5 'Tween deck plant) * Lloyd's RMC 12.54.


†
"to maintain temperature 15°F. with sea temperature 86° F. maximum".

Eck

27.1.55.

Note for Register Book

Insert additional items as per
Rotterdam Report.



© 2020

Lloyd's Register
Foundation

005107-005117-0182