

20 NOV 1956

SHIPS NAME "HOLDERNIDD" REPORT Ips No. 134596.  
JD.

Outstanding Conditions of Class: Subject to indented or set in  
bottom shell plates D.2 & E.3(p.s.f.) and C.1, D.2 & E.3  
(s.s.f.) being examined and dealt with as necessary by  
next drydocking.

Endorsement of Class (B) (As before ~~XXXXXX~~)

Nature of Present Survey: (Afloat and ~~in dry dock~~)


Temporary repairs (cement box) fitted to side shell  
leakage in way of No.2 hold (p.s.).

Recommendation:

SUBMITTED the ship is eligible to remain  
as classed, SUBJECT as above, and to permanent  
repairs being effected to defective shell plate  
(leakage) in No.2 hold (p.s.) on ship's arrival  
in the River Tees.

As Now. Subject.

ENDORSEMENT OF CLASS(B).  
Indents in keel plate No.2(aft)  
and adjacent strake(p.s.a.).



© 2020

Lloyd's Register  
Foundation

U/S Mdb 9/11/56  
M  
20.11.56