

Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

RE Steel S.S. "TREGONELL"

Rpt. Nwc.

No. 72635

of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also pointing out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points noted in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

First Entry.

Before this case reaches the consideration of the Committee the Surveyors are requested to state whether the breadth of upper deck stringer plate, of upper deck plating clear of bridge & thickness of <sup>deck</sup> plating abreast hatchways is approved for the standard "B" type vessel.

*no letter*

*M. AEB.*

© 5/20 2020



Lloyd's Register Foundation