

# Lloyd's Register of Shipping.

Ship's Name s.s. "TEVIOT"Official No. 169178

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines  
in \_\_\_\_\_

The following alterations have been carried out at this time:-

## SIDELIGHTS.

3 Sidelights in ship's side in way of No.6 tween deck Frs.12-18 (p.s.) have been blanked off. ✓

## SANITARY DISCHARGES.

The following overboard discharges have been removed and the openings in shell above 2nd deck have been blanked off:-

1 W.C. discharge Frs. 17-18 (p.s.) ✓

1 Sink discharge Frs. 19-20 (s.s.) ✓

1 Wash basin discharge Frs. 16-17 (p.s.) ✓

The following overboard discharges, fitted with storm valves (brass) on ship's side above 2nd deck, have been added at this time:-

1 Discharge, 4" diameter bore, from new crew's W.C. in No.6 tween deck, fitted between Frs.18-19 (p.s.) ✓

1 Discharge, 2" diameter bore, from new crew's washplace aft on Freeboard Deck, fitted between 1st and 2nd Frs. abaft transom. ✓

*W. A. Bomack*

Surveyor to Lloyd's Register of Shipping,

L O N D O N,

8th October, 1946.

A copy of this report has been put on board the vessel.

*Noted.*  
*gaw*  
11 OCT 1946