

25 AUG 1966

SM. Ship's name "NICOLAOS SARDIS"  
ex "TASSIA"

Port.

No. 12588

Last survey date 9.8.66

Class is subject to a bower anchor being supplied at the earliest opportunity and to total length of chain cable on board being verified and found or placed in accordance with Rule requirements next drydocking.

S.R.L. Appendix (as before ~~xxxxxxx~~)

Nature of present survey (afloat ~~and xxxxxxx~~)

Deferred repairs to damaged stem plating.

Recommendation

SUBJECT as above and to indented stem plating between 17 and 21 ft. draught marks being specially examined and dealt with as necessary next drydocking.

As Now. Subject

IN S.R.L. APPENDIX

Indented shell plating (p) and stem plating in way of 13' draught mark.

TO NOTE		TRO
<del>S. PLANS</del>	<del>S. RESEARCH</del>	<del>S. DEVELOP.</del>
<del>FREEBOARD</del>	<del>E. REPORTS</del>	<del>PHYS.</del>

JL  
24/8/66