

Rpt. 9B

## REPORT OF MACHINERY SURVEYS AND REPAIRS

FOR CONSIDERATION BY THE COMMITTEE OF LLOYD'S REGISTER OF SHIPPING

Received London

-6. DEC 1965

Ship's Name ~~SS/MS~~ "TASSIA"  
LR. 501914

Gross tons 2321

Port of Registry Piraeus.

Port HULL.

Date of build 1961.5?

Is there a rpt. 8? No.

Rpt. No. 71048

No. of visits One.

First date and

Last date 10/11/65.

Interim Cert. issued &amp; copy herewith? Yes.

Damage rpt. issued &amp; copy herewith? No.

Last rpt. (H.Q. only) 965 96530

Date of completing rpt. 1/12/65.

Surveyed at, if different from Port above

Is a rpt. 9A attached? No.

MN 306

Nature of survey S.V. adjusted under stm.

Survey fees

Damage fee

Expenses 6s.

Condition of Class. #5.

S.A. fee

## DOCKING

Propeller

Sea connections

Oil gland

Fastenings

Wear down of stern bush  
(if relined, state clearance  
before and after)Has screw/tube  
shaft been drawn?

Date of examn.

Has shaft been  
changed?

Has shaft now fitted been previously used?

Has shaft now examined/fitted a continuous liner?

Approved oil gland?

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS

(State if oil fired—OF  
or exhaust gas—EG)

MAIN

Air heaters

Superheaters

Safety valves

Mountings, doors  
and fasteningsSafety valves { Sat  
adjusted to { SptBoiler securing  
arrangements

Main economisers

Steam heated  
steam generatorsForced  
circulating pumpsHave saturated steam pipes in cylindrical boiler  
smoke boxes been examined as required by the Rules?Exhaust gas heated economisers  
and their safety valves

Steam generator safety valves adjusted to

Funnel

Were oil burning system &  
remote controls examined  
in accordance with rules?

I recommend that the machinery of this ship remain as classed with/without fresh record of

Survey, without condition regarding the safety valve springs on the port  
main boiler, but subject to any other condition which may be attached to  
the ships class remaining as previously recommended.(Where conditions of class are recommended to  
be retained, imposed, amended or deleted, particulars  
must be stated above and on the interim certificate.)

Surveyor to Lloyd's Register of Shipping

Date of Committee

TUESDAY 28 DEC 1965

Minute

note / mbs  
write theAsnow, subject  
mbs. 565

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

13 DEC 1965

RAB Bank 2020  
Lloyd's Register  
FoundationFOR CHAIRMAN  
CLASSN. CTTEE

30 DEC 1965