

XXXXXXXXX

8.10.65

GLASGOW

TASSIA

2321

See No.241

See No.241

Indented shell plating (p.s.) and stem plating in way of 13' draft mark.

M.E attached pumps disconnected 5.65

Nil

4 But ES 5.65

S.S. due 5.65 and completed 5.65 except for the hull condition of class.

MBS due 4.65

N.A



© 2020

Lloyd's Register
Foundation

005174-005179-0280