

PT

COPY

27 JUL 1965

Ship's name "TASSIA"Port

PIR

No. 11689Last survey date 5.5.65Class is subject to

indented shell plating (p.s) and indented stem plating in way of 13' draft mark being specially examined and dealt with as necessary next drydocking, and to 45 fathoms of chain cable (supplied 1962) being verified with test certificates at the earliest opportunity, and to a bower anchor and 15 fathoms of chain cable being supplied at the earliest opportunity.

S.R.L. Appendix (as before ~~xxxxxxx~~)

Surveys due SPECIAL SURVEY (C) due 5,65. Postponement until 5,66 approved 2.2.65 provided a satisfactory G.E. is held in drydock.

Nature of present survey (afloat and in drydock)

Docking.

Special Survey(except for condition of class re equipment), and repairs.

Is interim certificate in order~~xxx~~/No/~~xxxx~~Items outstanding ~~xxxxxx~~ for SS

Equipment as per condition of class.

SS proposed to be completed by

Recommendation SUBMITTED record of DS 4,65 be assigned, subject to 45 fathoms of chain cable (supplied 1962) being verified with test certificates and to 90 fathoms of chain cable (worn) being renewed at the earliest opportunity, without other conditions but further ACTION & NOTATION of SS 5,65 be DEFERRED for completion of S.S.(Equipment).

DS 4,65 subject.

INSERT IN S.R.L.APPENDIX

Indented shell plating (p.s) and stem plating in way of 13' draft mark.

IT IS FURTHER SUBMITTED the Surveyors be informed that the 45 fathoms of chain cable (supplied 1962) and reported as having been verified by the Turkey Surveyors in 11,63 is still outstanding.

In this connection the Interim Certificate of ^{TURKU}~~Turkey~~ dated 2.12.63 reported as having been sighted from which they state the 45 fathoms of chain cable was verified was superceded by an amended Interim Certificate which includes this item as still outstanding.

GD-22/6/65



© 2020

Lloyd's Register
Foundation