

Ship's name TASSIA 14 MAY 1964 Port Piraeus No. 10922
Last survey date 13.4.64
Class is subject to

1. Evaporator not being used until surveyed.
2. Superheaters of both boilers be renewed at earliest opportunity.
3. The ballast pump water end be renewed at the next Special Survey.

MBS due 11.64 now held.
On account of boilers were steamed
with sea water feed.
Port boiler number of tubes
expanded.
Starboard boiler all plain tubes & 6
stay tubes renewed
New tubes were not available with
L.R. certificates so flattening & expanding
tests were carried out on available
tubes made by 'Mannesmann Röhrenwerk
Ramscheid'.
SRC item 2 all superheater ~~tube~~ elements
renewed.
Boilers hydraulically tested on
completion of repairs & renewals.
ES now commenced
Minor repairs and renewal to
main & aux. machinery
SRC item 3 now deck ~~work~~
renewal.

Ship's name

TASSIA

Port

No.

Last survey date

Class is subject to

Surveyor reports I. P. piston valve
cracked now repaired by Mahalock
and recommends be re-examined
by 10.69

It is submitted that the
vessel WILL BE eligible
for the record ES (with date)
when the survey has been
completed. & MBS 4/64 ^{now} subject to item 1 above
and as recommended without subject to
items 283

leg

13/5/64



© 2020

Lloyd's Register
Foundation