

COPY

Ship's name TASSIA

Port

Piraeus

No. 10922

Last survey date 13.4.64

Class is subject to

1. Evaporator not being used until surveyed.
2. Superheaters of both boilers be renewed at earliest opportunity.
3. The ballast pump water end be renewed at the next Special Survey.

MBS due 11.64 now held.
On account of boilers were steamed
with sea water feed.

Port boiler number of tubes
expanded.
Starboard boiler all plain tubes & 6
stay tubes renewed
New tubes were not available with
U.R. certificates so flattening & expanding
tests were carried out on available
tubes made by 'Mannesmann Röhrenwerk
Ramschaid'.

SRL item 2 all superheater ~~tube~~ elements
renewed.

Boilers hydraulically tested on
completion of repairs & renewals.

ES now commenced
Minor repairs and renewal to
main & aux. machinery

SRL item 3 now deck
renewal.

COPY

Ship's name

TASSIA

Port

No.

Class is subject to

Last survey date

Surveyor reports E. P. piston valve
checked now repaired by Metablock
and recommends be re-examined
by 10.64

It is submitted that the
vessel **WILL BE** eligible
for the record *ES (with data)*
when the survey has been
completed.

MBS 4/64 now subject to item 1 above
and as recommended without subject to
items 2 & 3

MS

13/5/64



© 2020

Lloyd's Register
Foundation