

COPY

Ship's name TASIA

Port Lisbon

No. 10418

Last survey date 29.1.64

Class is subject to

1. Evaporator not being used until surveyed.
2. Superheaters of both boilers be renewed at earliest opportunity.

On account of contamination of the feed water by salt water
Condenser examined and a number of leaking tubes now
plugged. boiler cleaned on water side and some mountings
and feed pipes examined and overhauled where necessary.
Some wear & tear repairs effected.

The ballast pump water end examined and defective valve
seats found plugged with wood. also various parts of the
section a delivery valve unit found missing. also the
division plates eroded. The Surveyor recommends
the ballast pump water end be renewed at the next
Special Survey

It is submitted that this
vessel is fit to remain
as CLASSED.

Subject as above
and as now
recommended.

LD
6/3/64



© 2020

Lloyd's Register
Foundation

005174-005179-0347