

113 JAN 1964

Ship's Name SS/MS TASSIA ex. Annette Gross tons 2321

Is there a rpt. 9? No Port ÅBO Rpt. No. 1023

No. of visits 6 First date 2.12.63 Last date 14.12.63

Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only) ABO 1018

Date of completing rpt. 20.12.63 Surveyed at, if different from Port above

Surveyed afloat and/or in D.D. Afloat Last date of examination in D.D.

Has a Load Line Survey been held? Yes Renewal Freeboard Marks verified Yes and changed to Greek lettering

State which additional Rpt. 8 is attached: ~~(Cot)~~; (PS); ~~(DR)~~; ~~(EQ)~~; ~~(Rig)~~

Survey fees Damage fee Expenses 16.-

Freeboard 170.- see Form C.11(b) *She*

S.A. fee 99.-

115 JAN 1964

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due

I have surveyed the above ship in accordance with the Rules for Load Line Survey when changing of nationality.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. No repairs effected, all placed in order at DS and Annual survey.

I recommend that this ship remain as classed ~~with~~ without fresh record of ~~downlocking~~ survey subject to all outstanding conditions of class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee THURSDAY - 6 FEB 1964
Minute DS 11.63 subject

[Signature]
Surveyor to Lloyd's Register of Shipping

ALSO FOR
SPL FOR
TRO
SRL ✓
POSTING
HEADER
CERT

Lloyd's Register Foundation

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC. The reason for repairs must be stated and repairs on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs and, besides being detailed above, should be noted in the following summary. *State what action has been taken regarding items which are subjects of class or in SRL Appendix, whether outstanding or new.* Any alterations in existing particulars in the Register Book should also be reported above.

SUMMARY OF DAMAGE REPAIRS	SHELL PLATES	FRAMES	DECK PLATES	BEAMS	OTHER ITEMS
Renewed					
Removed and faired or replaced					
Faired or repaired in place					



© 2020

Lloyd's Register
Foundation

Rpt. 8 (P.S.) DRY CARGO SHIP

Ship's Name SS/MS TASSIA ex. Annette S.S. () Due

Port ÅBO Rpt. No. 1023

<u>Examined & condition</u>	<u>Examined & condition</u>
In dry dock from	* Air & sounding pipes Good
„ „ „ to	Doublers under „ „
Shell plating	Steering arrangements (main) Good
Sternframe	„ „ (aux) Good
Rudder	Windlass
Was rudder lifted?	Masts & rigging
Plating, etc. in way of shell openings	Hand pumps & suction
Side scuttles & deadlights Good	W.T. doors Good
Overbd. scuppers & discharges Good	Bulwarks, freeing ports, etc. Good
F.P. spaces	Summer freeboard as verified 470 mm
Chain locker	
A.P. spaces	
Engine space	
Boiler space	
Under E. & B.	
Coal bunker	
Tunnel & well	
Cement, asphalt, etc., on btm. shell	
Weather decks Good	
* Casings Good	
* Deckhouses Good	
* Superstructures Good	
* Skylights Good	
* Companionways Good	
* Hatchways Good	
* Ventilators Good	
Other items:	

EQUIPMENT:

Equipment letter
 Fee ltr., if diff. from eqpt. ltr.
 Anchors: No. on board
 State if ranged
 Length on board
 Mean dias. range from to
 Rule length Dia.
 Mooring ropes

* These items to include their closing appliances
 Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"



© 2020

Richard Stignell
 Surveyor to Lloyd's Register of Shipping
 Foundation

005174-005179-0357 1/2

HOLDS & 'TWEEN DECKS:		Examined & condition	TANKS:	Examined & condition	Tested & condition
No. 1	Hold		F.P. tank		
„	'Tween decks		A.P. tank		
			D.B. tanks & c/dams		
No. 2	Hold				
„	'Tween decks				
No. 3	Hold		O.F. bunkers		
„	'Tween decks				
			Settling tanks		
No. 4	Hold				
„	'Tween decks				
			Deep tanks		
No. 5	Hold				
„	'Tween decks		Side tanks		
No. 6	Hold		Wing tanks		
„	'Tween decks				
			Other tanks:		
	Cargo battens				
	Ceiling, etc.				



© 2020

Lloyd's Register
Foundation