

EA

COPY

Ship's name "ANNETTE"

Port

ABO

No 018

Last survey date 30.11.63.

Class is subject to

indented shell plating (p.s) being specially examined and dealt with as necessary next drydocking, and to 45 fathoms of chain cable being examined at the earliest opportunity.

S.R.L. Appendix (as before or none)

Nature of present survey (afloat and in drydock)


Docking:

Equipment: ship found to have a full Rule length of chain cable on board and 45 fathoms of chain cable as above were stated to have been placed on board in 1962 without the Surveyor being in attendance - no tests certificates available

Recommendation

SUBMITTED record of DS 11,63 be assigned, subject to indented shell plating (p.s) and indented stem plating in way of 13' draft mark being specially examined and dealt with as necessary next drydocking, and to 45 fathoms of chain cable (supplied 1962) being verified with test certificates at the earliest opportunity.

DS 11,63 Subject amended.



Lloyd's Register
Foundation