

15 SEP 1958

Received from Chief Ship Surveyor

SHIP'S NAME "MIRIELLA"

REPORT

Nap.

No. 6666

standing Conditions of Class:Subject to shell plate E.9 (p.s.)
being dealt with as necessary next drydocking.Improvement of Certificate (As before ~~or None~~)Area of Present Survey: (Afloat and in dry dock)

Drydocking: Repairs to shell plating (deferred item above).

Recommendation:SUBMITTED record of 'DS 8,58' be assigned
as recommended, but without special condition.

DS 8,58 Without.

S.R.L. APPENDIX NOTElight indents in sheerstrake 1st below and bulwark
(s.s.f.) slightly set in.

© 2020

Lloyd's Register
Foundation

k(new)

005187-005193-0102