

1 E

Inspected by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

VESSEL'S NAME "MITRA" REPORT Rot. No. 31980


Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Type of Engine Oil Engine 4 S.C.S.A.

8 Cyl.  $25\frac{9}{16}$ " -  $55\frac{1}{8}$ "

MN 617


~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner Yes

If fitted with an outside gland of approved type No

The torsional vibration characteristics of the main propelling machinery were approved in the Secretary's letter of 3. 11. 48 for a service speed of 120 R.P.M.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is

eligible to be classed  LMC 12.49

"Carrying petroleum in bulk"

2 DB 180 lb.

Emk


27. 2. 50.



© 2020

Lloyd's Register  
Foundation

005187-005193-0145

That provision is made for first Charging the Air Receivers  steam compressor