


COPY

LLOYD'S REGISTER OF SHIPPING

No. H-1137



Port..... Hakodate

Date..... 8th April, 1966

This is to Certify that I have

surveyed the M.S. "PHOENICIAN STAR" *gross tons* 4,982 of Panama
whilst lay afloat at Muroran on the 7th April, 1966 on account
of cant shell leakage

and that I am transmitting to the Committee of Lloyd's Register of Shipping, London, a report, stating that all repairs recommended by me have been completed to my satisfaction, also that I am recommending that she be remained as now classed without fresh record of survey subject to stern cant shell (port side) holed now temporarily repaired being permanently repaired at next drydocking and to any condition at present attached to class being dealt with as previously recommended.


K. Ikehata
Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

AS Annual Survey
BiS Biennial Survey
DS Docking Survey
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey
SS(Dr) Hull Special Survey (Drilling)
SS(M) Hull Special Survey (Modified)
CSH Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, but it is to be understood that neither the Society nor any Member of any of its Committees nor any of its Officers, Servants or Surveyors is under any circumstances whatever to be held responsible or liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any act or omission, default or negligence of any of its Committees or any Member thereof, or of the Surveyors, or other Officers, Servants or Agents of the Society."

N. Cert. B 240m,9,65 (MADE AND PRINTED IN ENGLAND.)

005187-005193-0228