

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

7th January, 1966.

C
DNS/SO

Dear Sirs,

M. V. "PHOENICIAN STAR".

Before your Report No.15181 receives the consideration of the Committee, I shall be glad to learn:-

1. Whether the screwshaft was crack detected in accordance with the Rules for four yearly Screwshaft Surveys.
2. In view of the fact that the sternbush was rewooded in June, 1965, to 1.2 mm clearance, whether you can state the reason for the rapid wear down.
3. In view of the fact that there is no information in this Office regarding any temporary cables being fitted in the holds, can you state when these were fitted and also the reason.
4. It is concluded that all temporary cables have now been completely disconnected and replaced with cables which comply with the Rules, but your confirmation is desired.

With regard to the Report 8, it is concluded that none of the items examined at this time is to be credited towards the Special Survey, but this should be confirmed.

ANSWER TO BE
SHOWN TO MR N. CHAMBERLAIN RE TO

005187-005193-0260 1/2

Lloyd's Register
Foundation

(2)

An early reply will be appreciated.

Yours faithfully,

ce *EL. LTR. FILE*

Assistant Clerk to the
Classification Committee.

The Surveyors,
HAMBURG.



© 2020

Lloyd's Register
Foundation

0260 ½