


COPY

LLOYD'S REGISTER OF SHIPPING



Port.....Hamburg.....

Date.....11th, November, 1965.....

This is to Certify *that I have surveyed part of the machinery of the MS. PHOENICEAN STAR. 4925. gross tons PANAMA. LR. 530973.*

for General examination for postponement of Special Survey-CSM-TS-Docking and repairs. Whilst the ship lay afloat and in dry dock on the 4th, October, 1965, and subsequently to the 3/11/65.

and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned TSCL-10/65-CSM (with date) upon completion of the Survey, subject to electrical cables in holds being dealt with as found necessary by end of 8/66, and subject to any outstanding condition of class being dealt with as previously recommended.

Parts now examined:—

Main Engine:—

Nos. 2 & 3 Cylinder Liners, top and bottom pistons, transverse beams and bottle guides with rods.
Valves and valve gears.
Centre and side crossheads, guides and bearings and connecting rods.
Centre and side crankpins and bearings.
Nos. 1-3-&-4, main bearing and journals.
Aft Auxiliary Generator Engine over all parts.

Docking:—

Ship placed in dry dock, Propeller, Screwshaft, Sternbush and outside fastenings of sea connections.

A. Knauer K.D. Nishen
(A. Knauer & K.D. Nishen)
Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150°F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

Re. While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."