

14-6-65

Ship's Name SS/XX "SYCAMORE HILL" LR 534703 Gross tons 7126

Is there a rpt. 9? Yes

Port Calcutta

Rpt. No. 1778

No. of visits 6

First date 27.5.65

Last date 3.6.65

Interim Cert. issued  
& copy herewith?

Yes

Damage rpt. issued  
& copy herewith?

Last rpt. (H.Q. only)

for 16/2/5

Date of  
completing rpt.

4.6.65

Surveyed at, if different from Port above

Surveyed afloat  
and/or in D.D.

Afloat

Last date of examination in D.D. -

Has a Load Line  
Survey been held?

Yes, Annual

Freeboard Marks verified Yes

State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig)

Survey fees

Damage fee

Expenses

Rs. 1400/-

Rs. 90/-

Cablegram Rs. 25/-

S.A. fee Rs. 100/- (30.5.65)

I have surveyed the above ship in accordance with the Rules for Annual Load Line Survey, Advancement of General Examination afloat for postponement of SS type C Vessel 21 years old (SS due 7/65). for 12 months.

London Cable 28.5.65 refer.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. The advancement of the General Examination afloat has now been carried out in accordance with instructions to Surveyors Part 3a 1963 for vessels over 14 years old.

In view of the satisfactory examination now held afloat the Owner's request for postponement of the Special Survey (due 7/65) for 12 months is submitted for the favourable consideration of the Committee when the after Peak Tank has been examined internally.

The Master stated that the after Peak Tank would be examined in Penang to which port the vessel is proceeding direct.

CONDITION OF CLASS NO.235

- 1) Drydocking (grounding)
- 2) Rivetting in shell bilge seam in way of No.3A hold (SS) to specially examine next drydocking.

P.T.O.

I recommend that this ship remain as classed ~~xxx~~/without fresh record of ~~xxxxxx~~ Survey, subject to any outstanding Conditions of Class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee MONDAY 12 JUL 1965

Minute

As now, subject (m)

D. VINCENT.

Surveyor to Lloyd's Register of Shipping

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

FOR CHAIRMAN  
CLASS. CITEE.

005187-005193-0436 1/2

and action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

due date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the



- 3) Damaged stem and stem plating to be dealt with on arrival Liverpool.

It was stated by the Master, to the best of his knowledge that these conditions had been dealt with recently at Liverpool when a date of DS 3/65 was assigned without special Condition.

APPENDIX LIST No.15

Slightly corrugated bottom shell plating to be kept under observation at each drydocking.

Not examined at this time, vessel afloat.

**PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.** The reason for repairs must be stated and repairs on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs and, besides being detailed above, should be noted in the following summary. *State what action has been taken regarding items which are subjects of class or in SRL Appendix, whether outstanding or new.* Any alterations in existing particulars in the Register Book should also be reported above.

SUMMARY OF DAMAGE REPAIRS	SHELL PLATES	FRAMES	DECK PLATES	BEAMS	OTHER ITEMS
Renewed					
Removed and faired or replaced					
Faired or repaired in place					



© 2020

Lloyd's Register  
Foundation



## Rpt. 8 (P.S.) DRY CARGO SHIP

Ship's Name SS/MS "SYCAMORE HILL"

S.S. ( 7/61 ) Due 7/65

Port CALCUTTA

Rpt. No. 1778

<u>Examined &amp; condition</u>		<u>Examined &amp; condition</u>	
In dry dock from		*Air & sounding pipes	Good above deck
" " " to		Doublers under	Good (No. 6 P&S DBS)
Shell Plating	DS 3/65	Steering arrangements (main)	Good
Sternframe	Liverpool	" " (aux)	Good
Rudder		Windlass	Good
Was rudder lifted?		Masts & rigging	Good from deck for GE
Plating, etc. in way of shell openings		Hand pumps & suction	Good
Side scuttles & deadlights	Good	W.T. doors	Good
Overbd. scuppers & discharges	Good	Bulwarks, freeing ports, etc.	Good for GE
F.P. spaces	Good for GE	Summer freeboard as verified	10' 6½"
Chain locker	not examined		
A.P. spaces	not examined		
Engine space	good for GE		
Boiler space	good for GE	<u>EQUIPMENT :</u>	
Under E. & B.	good for GE	Equipment letter	CT6762 C37
Coal bunker	None	Fee ltr., if diff. from eqpt. ltr.	S33
Tunnel & well	good for GE	Anchors : No. on board	3B
Cement, asphalt, etc., on btm. shell	Good (No. 6 P&S DBS)	Cables { State if ranged	No
Weather decks	Good	Length on board	Stated complete
*Casings	Good	Mean dias. range from	to
*Deckhouses	Good	Rule length	270 FMS Dia. 2.1/16"
*Superstructures	Good	Mooring ropes	Sufficient
*Skylights	Good		
*Companionways	Good		
*Hatchways	Good		
*Ventilators	Good		
Other items :			

\*These items to include their closing appliances

Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"



© 2020

D. VINCENT

Surveyor to Lloyd's Register of Shipping



HOLDS & 'TWEEN DECKS:		Examined & condition	TANKS:	Examined & condition	Tested & condition
No. 1	Hold	-	F.P. tank	Good	For GE
"	'Tween decks	-	A.P. tank		
			D.B. tanks & c/dams		
			No. 6(P&S)FW	Good	For GE
No. 2	Hold	Good for GE	Good for GE		
"	'Tween decks	Good for GE			
No. 3	Hold	Good for GE	O.F. bunkers		
"	'Tween decks	Good for GE			
			Settling tanks		
No. x 3A	Hold	Good for GE			
"	'Tween decks	Good for GE			
			Deep tanks		
No. x 4	Hold	Good for GE			
"	'Tween decks	Good for GE	Side tanks		
No. x 5	Hold	Good for GE	Wing tanks		
"	'Tween decks	Good for GE			
			Other tanks:		
	Cargo battens	Good for GE			
	Ceiling, etc.	Good for GE			



© 2020

Lloyd's Register  
Foundation