

PT

4 FEB 1965

Ship's name "SYCAMORE HILL" Port RR No. 120

Last survey date

Class is subject to

riveting in shell bilge seam in way of No.3A hold (s.s) being specially examined and dealt with as necessary at thenext drydocking.

ACTION is DEFERRED for examination in drydock after grounding.

S.R.L. Appendix (as before of ~~XXXXXX~~)

Nature of present survey (afloat and in drydock)

Damage (contact) involving stem and stem plating.
Temporary repairs.

Recommendation

SUBMITTED ACTION continue to be DEFERRED for examination in drydock after grounding, subject as above and to damaged stem and stem plating being specially examined and dealt with as necessary on ship's arrival at Liverpool from present voyage.

SUBJECT

IN S.R.L. APPENDIX

(Slightly corrugated bottom shell plating to be kept under observation each drydocking).

IN S.R.L

Drydocking (grounding).

PORT - MURMANSK

© 2020

Lloyd's Register
Foundation