

m, 1, 60

Class is subject to Windlass steam block being removed by 11.60 (9 mos. limit)

4E

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

6- JAN 1961

SHIP'S NAME SARONA REPORT Singapore No. 14414

SRL. The above item dealt with & replaced block found working satisfactorily.

It is submitted that this vessel is eligible to remain as classed without special condition regarding windlass steam block.



© 2020

Lloyd's Register
Foundation

005194-005209-0024