

1

12 NOV 1934

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Stl Sc.K. "ORVICTO" Report \_\_\_\_\_ Lon \_\_\_\_\_ No 100493a**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/34)

Nature of Survey \_\_\_\_\_ When due \_\_\_\_\_

The Boiler Survey became due in 9,34.

In reply to the usual notice the Owners write that they do not desire to keep this trawler in classification and they ask that the class be deleted.

It is submitted the class of this trawler be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at the Owners' request.

Withdraw class

Insert ...



© 2020

Lloyd's Register  
Foundation

005194-005209-0058