

Received from Chief Ship Surveyor

23 JAN

NAME  
JD.

"SHEILA PATRICIA"

REPORT

Hfx.No. 7323.

ending Conditions of Class:

(s.s.) being examined and dealt with as necessary by 12,57( 4 mos. limit). Subject to indented stem plating

ment of Class (B) (As before ~~or None~~)

of Present Survey: (Afloat and ~~in dry dock~~)

Satisfactory examination of temporary repairs to forward shell plating, etc.

ndation:

SUBJECT to indented stem plating, etc.  
(s.s.) being examined and dealt with as necessary  
next drydocking, with Endorsement of Certificate.

As Now. Subject  
Amended.

ENDORSEMENT OF CERTIFICATE.

Rudder stock twisted 7°.



© 2020

Lloyd's Register  
Foundation

005194-005209-0106