

Received by Chief Ship Surveyor .....

Received from Chief Ship Surveyor 16 OCT 1958

GB

SHIPS NAME

"REMEDIOS"

REPORT

Bcl.

No.

6837

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class of this ship #100A1 "Carrying Petroleum in Bulk" was expunged from the Register Book 10,57 for non-compliance with the Rules.

Reclassification with the Society is now desired.

The BARCELONA Surveyor reports (5,58), this ship afloat and the RECLASSIFICATION SPECIAL SURVEY (D) commenced by the drilling of the weather deck and part drilling of the shell plating.

The Surveyor indicates in the report the repairs/renewals required so far to be done before the ship could be reclassified. It is noted from Barcelona letter dated 13.8.58 attached to the case that the Owners have suspended the survey pending a decision as to whether it should be continued or not.

IT IS SUBMITTED ACTION be DEFERRED pending further information.

IT IS FURTHER SUBMITTED the Surveyors be advised it is concluded that the renewals enumerated in the report include 'H' strake (p & s) in way of No.7 tank (drillings 9 & 9.5 m/m. respectively), also 'J' strake (p.s.) in way of No.1 tank (drilling 9.2 m/m.).

WRECK  
SECTION

No 862

13

RMF.  
10.9.58

28906

10/58

WRECK  
SECTION



© 2021

Lloyd's Register  
Foundation

005210-005218-0073