

56,525.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl Schooner* "DON JULIAN" Rpt. *Ans* No. 10388

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

18' Long

Transverse No.

913

Depth "d"

11.33

Framing: Table No.

Description

angle & half angle frame

Longitudinal No.

2592

as approved

Proportions

Length

5.84

Depth =

Beck Sheerstrake

as approved

Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100 A.1. (Steel) "For Fishing Services"

1 Dk.

B.K 5³/₄, 1 B.H, Cmn, Lloyd's A - CP.



© 2021

Lloyd's Register
Foundation

005219-005231-0234

" Breadth and thickness

" No. of Side Stringers, breadth and thickness

W T BULKHEADS

Inches. Inches.

and if w

IFFEN

l. Verti

Inch