

Lloyd's Register of Shipping.

FOUNDED 1760.

RE-CONSTITUTED 1834.

Certificate of Class

Steel Screw Steamer Bendoran ex Samdaunilless
 Official Number 169875 Port of Registry London
 Owners Ben Line Steamers Limited (Wm. Thomson & Co. Limited Managers)
 Builders, and where and when built Bethlehem Fairfield Shipyard, Inc. Baltimore, Md., 1944.

REGISTERED PARTICULARS.

Length <u>423.3</u> feet	Tonnage, Gross <u>7252.30</u>
Breadth <u>57.1</u> feet	Ditto under Deck <u>6683.14</u>
Depth <u>34.85</u> feet	Ditto Net <u>4418.49</u>

This is to Certify that this Vessel has been surveyed by the Surveyors to this Society, and was reported to be, on the 17th October, 1947 at Leith in a good and efficient state, and fit to carry dry and perishable Cargoes, and has been CLASSED and entered in the REGISTER BOOK of this Society, with the Character **100A1** "Carrying oil Flash Point above 150°F in deep tanks"
 FITTED FOR OIL FUEL. — FLASH POINT ABOVE 150°F.

Specially Surveyed Leith - 1947

subject to Periodical Surveys as required by the Rules, & to the tunnel W.T. door being altered to "Part Electrically Welded."

comply with the Rules at the first opportunity, & to the anchors being verified & their weights & particulars of ropes reported, also to 45 fathoms of chain cable being supplied at the first opportunity, & to a tower anchor being placed on board at the end of the present emergency.

Witness my hand,

Robert Clement

Secretary.


James H. Danks

Chairman.

71, Fenchurch Street, LONDON, 31st October, 1947

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



© 2021

Lloyd's Register
 of Shipping



© 2021

Lloyd's Register
Foundation

005219-005231-0239