

SEASON 1955/56

Report No. 548

'STORA"

DRILL TESTING OF SHELL PLATES

(Thicknesses are in hundredths of an inch)

Port Side:-Plates:-

A.1. 34.375 ✓	B.7. 31.250 ✓	C.12. 34.375 ✓	E.1. 43.750 ✓
A.2. 34.375 ✓	B.8. 32.812 ✓	D.1. 37.500 ✓	E.2. 40.625 ✓
A.3. 31.250 ✓	B.9. 34.375 ✓	D.2. 37.500 ✓	E.3. 37.500 ✓
A.4. 34.375 ✓	B.10. 43.750 ✓	D.3. 34.375 ✓	E.4. 34.275 ✓
A.5. 34.375 ✓	C.1. 43.750 ✓	D.4. 34.375 ✓	E.5. 34.375 ✓
A.6. 31.250 ✓	C.2. 50.000 ✓	D.5. 37.500 ✓	E.6. 31.250 ✓
A.7. 31.250 ✓	C.3. 50.000 ✓	D.6. 37.500 ✓	E.7. 34.375 ✓
A.8. 31.250 ✓	C.4. 34.375 ✓	D.7. 37.500 ✓	E.8. 31.250 ✓
A.9. 34.375 ✓	C.5. 31.250 ✓	D.8. 31.250 ✓	E.9. 28.125 ✓
A.10. 46.875 ✓	C.6. 32.812 ✓	D.9. 28.125 ✓	E.10. 23.437 ✓
A.11. 34.375 ✓	C.7. 25.000 ✓	D.10. 28.125 ✓	E.11. 25.000 ✓
A.12. 37.500 ✓	C.8. 28.125 ✓	D.11. 23.437 ✓	E.12. 25.000 ✓
A.13. 34.375 ✓	C.9. 31.250 ✓	D.12. 25.000 ✓	
A.14. 31.250 ✓	C.10. 31.250 ✓		
A.15. 34.375 ✓	C.11. 28.125 ✓		

Starboard Side:-Plates:-

A.1. 37.500 ✓	B.7. 31.250 ✓	C.12. 35.937 ✓	E.1. 46.875 ✓
A.2. 34.375 ✓	B.8. 43.750 ✓	D.1. 34.375 ✓	E.2. 40.625 ✓
A.3. 31.250 ✓	B.9. 34.375 ✓	D.2. 37.500 ✓	E.3. 37.500 ✓
A.4. 31.250 ✓	B.10. 46.875 ✓	D.3. 31.250 ✓	E.4. 31.250 ✓
A.5. 34.375 ✓	C.1. 50.000 ✓	D.4. 50.000 ✓	E.5. 34.375 ✓
A.6. 34.375 ✓	C.2. 50.000 ✓	D.5. 31.250 ✓	E.6. 37.500 ✓
A.7. 31.250 ✓	C.3. 50.000 ✓	D.6. 37.500 ✓	E.7. 37.500 ✓
A.8. 34.375 ✓	C.4. 37.500 ✓	D.7. 37.500 ✓	E.8. 34.375 ✓
A.9. 34.375 ✓	C.5. 31.250 ✓	D.8. 25.000 ✓	E.9. 31.250 ✓
A.10. 50.000 ✓	C.6. 34.375 ✓	D.9. 28.125 ✓	E.10. 28.125 ✓
A.11. 32.912 ✓	C.7. 28.125 ✓	D.10. 28.125 ✓	E.11. 25.000 ✓
A.12. 37.500 ✓	C.8. 31.250 ✓	D.11. 28.125 ✓	E.12. 21.875 ✓
A.13. 31.250 ✓	C.9. 29.687 ✓	D.12. 21.875 ✓	E.13. 25.000 ✓
A.14. 32.812 ✓	C.10. 31.250 ✓		
A.15. 31.250 ✓	C.11. 28.125 ✓		

South Georgia,
11/55. R.

Surveyor to Lloyd's Agent.

005239-005248-0192