

Lloyd's Register of Shipping.

21 JUN 1948

Ship's Name.....S. S. "LAKE COWICHAN".....Official No. 176011

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines
in.....MARCH, 1945.....

ALTERATIONS NOW DONE:-

The gunners' accommodation in the 'tween deck space at No. 5 hatch has
now been removed.

The fore and aft casing at the hatch side has been removed from Frame No. 22
to the forward bulkhead.

The casing at Frame 22 port side has been made continuous to the fore and
aft casing at the hatch side.

The following ventilators in way No. 5 'tween deck now removed and holes
efficiently blanked:-

2 pcs. 6" dia. located on the upper deck port side forward.

1 pc. 6" " " " " " " " aft.

1 pc. 10" " " " " " " " forward.

Portlights - 8 portlights in No. 5 'tween deck port side now removed complete
and holes in shell efficiently plated over.

Waste Water Discharge - one from gunners' wash room now removed and hole in
shell efficiently plated over.


Decks, casing and shell hose tested on completion and found tight.

J. H. W.
SURVEYOR TO LLOYD'S REGISTER OF SHIPPING

Vancouver, B. C.

17th May, 1948

A copy of this report has not been placed on board, the vessel being of
Canadian Registry.



© 2020

Patel.
G.H.W.
Lloyd's Register
Foundation
22 JUN 1948